

This may unscrew, allowing access to grub screws from top, not just the rotary tension. Removing should allow shaft to be viewed

Is there a screw back here?

If there are no grub screws from top, or screws on the back side of the handle, it will likely need to twist apart

